
Vib@Work™

**Calibration check of dosimeters measuring whole body vibrations.
Calibration check bench user manual**

Version 1.1



TABLE OF CONTENTS

SECTION 1 - DESCRIPTION	1
1.1 PRINCIPLE	1
1.2 PRACTICAL SEQUENCE	1
1.3 CHECK BENCH COMPOSITION	2
SECTION 2 - INSTALLATION AND CONFIGURATION.....	3
2.1 CONTENT OF THE KIT.....	3
2.2 PREREQUISITES.....	3
2.3 INSTALLATION.....	3
2.3.1 INSTALLING THE WBCHECK SOFTWARE.....	4
2.4 CONFIGURING THE WBCHECK SOFTWARE.....	4
2.4.1 MANAGING THE SENSORS	5
SECTION 3 - USE	8
3.1 PREREQUISITE CHECKS AND RECOMMENDATIONS.....	8
3.2 LEVELLING OF THE BASE	9
3.3 POSITIONING OF THE DEVICE TO BE CHECKED ON THE SENSOR FRAME.....	10
3.3.1 "SEAT" SENSOR.....	10
3.3.2 "FLOOR" SENSOR.....	10
3.4 RUNNING THE CHECK SEQUENCE	11
3.4.1 CONNECTING THE SENSOR	11
3.4.2 THE 6 POSITION MEASUREMENTS	12
3.5 DISPLAYING THE RESULTS.....	15
SECTION 4 - UPDATING OF THE WBCHECK SOFTWARE	17
SECTION 5 - SUPPORT	18

Section 1 - Description

1.1 Principle

The check bench for “whole body” dosimeters allows the acceleration measurement of “seat” or “floor” sensors to be validated along the 3 measurement axes X, Y and Z.

The sensor to be checked is placed into a mode that allows its acceleration due to the Earth's gravity ($g = 9.81 \text{ m/s}^2$) to be measured, which therefore serves as a reference. Each measurement axis is successively positioned along the vertical (perpendicular to the ground); the sensor measurement can then be compared to the acceleration of gravity g .

In practice, two measurements are taken per axis: one in the positive direction, the other in the negative direction. The difference between the two should provide a measurement within the region of $2g = 2 \times 9.81 \text{ m/s}^2 = 19.62 \text{ m/s}^2$

1.2 Practical sequence

The sequence is as follows:

1. The X axis of the sensor is aligned along the vertical in the positive direction (Measurement $X_+ \approx +g$)
2. The X axis of the sensor is aligned along the vertical in the negative direction (Measurement $X_- \approx -g$)
→ The difference between the 2 measurements $X_+ - X_-$ should be $2g$
3. The Y axis of the sensor is aligned along the vertical in the positive direction (Measurement $Y_+ \approx +g$)
4. The Y axis of the sensor is aligned along the vertical in the negative direction (Measurement $Y_- \approx -g$)
→ The difference between the 2 measurements $Y_+ - Y_-$ should be $2g$
5. The Z axis of the sensor is aligned along the vertical in the positive direction (Measurement $Z_+ \approx +g$)
6. The Z axis of the sensor is aligned along the vertical in the negative direction (Measurement $Z_- \approx -g$)
→ The difference between the 2 measurements $Z_+ - Z_-$ should be $2g$

1.3 Check bench composition

The “whole body” dosimeter check bench is made up of the following 3 elements:

1. A levelling base for obtaining a level work surface.
2. A sensor frame on which the sensor is fixed and allowing it to be positioned along the 6 measurement directions (X_+ , X_- , Y_+ , Y_- , Z_+ et Z_-).
3. Software (WBCheck) that provides guidance for positioning the sensor, collects the measurements in the 6 measurement directions and displays the results of the check.




Figure 1: “Whole body” dosimeter check bench

Section 2 - Installation and Configuration

2.1 Content of the kit

The kit contains:

- A levelling base made up of 2 spirit levels and 3 adjusting screws enabling horizontal alignment.
- A sensor frame to which a “seat” or “floor” sensor can be attached.
- A CD-ROM containing the software and user manual
- A quick installation guide



Figure 2: Kit

2.2 Prerequisites

Minimum configuration required for the PC:

- Windows XP® (Service Pack 2), Windows Vista® or Windows 7®
- Microsoft .NET Framework 3.5
- Hard disk drive with 20 Mb of available space
- CD-ROM reader
- VGA graphics card or compatible video graphics driver at up to 256K colours or higher
- Keyboard
- Microsoft mouse or compatible pointing device
- Bluetooth communication device

2.3 Installation

- Insert the CD-ROM supplied into your CD drive.
- The installation programme begins automatically if this option is authorised on your PC. If the installation programme doesn't start after a few seconds, display the CD-ROM contents and launch the "Start" programme.
- Follow the on-screen instructions.

2.3.1 Installing the WBCheck software

- Click on the "Installation of the WBCheck software" link; the WBCheck software installs on your PC and starts up automatically.
- The welcome screen is displayed (Figure 3)



Figure 3: Welcome screen

2.4 Configuring the WBCheck software

On the welcome screen, click on the "Next >" button. The screen below is displayed.




Figure 4: Sensor selection screen

The sensors that have already been configured are displayed in the list.

	Updating the software via the Internet will not alter the list of already configured sensors.
---	---

2.4.1 Managing the sensors

2.4.1.1 Adding a sensor

Prior to using your sensor, the data relating to it should be entered.

- Click on the  button. The sensor management window opens up (Figure 5). Here you will find a list of sensors that have been previously registered. If you are configuring your first sensor, this list will be empty.




Figure 5: Managing the sensors

- Click on the  button to add a sensor. A new window is displayed (Figure 6) allowing you to enter the data relating to the sensor.




Figure 6: Adding a sensor

- In the "Serial Number" field, enter your sensor's serial number (8 figures inscribed on the sensor casing).

- In the “software key” field, enter the key to allow the software to authorise the check of the device.
- In the “COM Port” field, enter the COM port number generated during the Bluetooth pairing of the device (output COM port).




Figure 7: Adding a sensor (2)



The software keys allowing you to check the calibration of the sensors can be obtained upon acquisition of a WBCheck licence. Please contact your distributor to find out the terms and conditions of acquisition and use.



The software keys for WBCheck are different from the keys used for obtaining vibration histories during ground measurements using your devices.

- When the fields are completed, validate them by clicking on the  button. The sensor selection window will then display the sensor that you have just entered.




Figure 8: Adding a sensor (3)

2.4.1.2 Deleting a sensor

- Click on the  button to access the sensor management window, which displays the list of sensors already registered.
- Select a sensor in the list by clicking on the corresponding row.
- Click on the  button to delete the selected sensor.
- Click on the  button to close the sensor management window.

2.4.1.3 Editing a sensor

- Click on the  button to access the sensor management window, which displays the list of sensors already registered.
- Select a sensor in the list by clicking on the corresponding row.
- Click on the  button to access the data relating to the selected sensor.
- Enter - for example - the sensor software key.
- Click on the  button to close the sensor management window.

Section 3 - Use

This section explains how to implement the “whole body” sensor calibration check bench.



The various stages are listed below. The majority of the stages are performed using the "WBCheck" software.


- Stage 1 - Prerequisite checks and recommendations**
- Stage 2 - Levelling of the base**
- Stage 3 - Positioning of the device to be checked (seat sensor or floor sensor) on the check bench**
- Stage 4 - Running of the check measurement sequence**
- Stage 5 - Displaying the results**

3.1 Prerequisite checks and recommendations

- Make sure that the dosimeters to be checked are sufficiently charged.
- Avoid checking devices in close proximity to strong hot or cold thermal sources.
- Carry out the check on a stable surface and in a calm vibration-free environment.
- The measurement sequence must be carried out in a single stage, with no interruptions. If you wish to interrupt the sequence after 2 minutes have elapsed, restart it from the beginning.
- Due to its technological implementation, the Bluetooth communication becomes less effective when 4 devices are activated within a radius of a few metres. This includes the sensors, the PC used to run WBCheck, as well as other devices external to the dosimeters (mobile telephones, earphones etc.). Check that there are not too many Bluetooth devices activated within a confined area. If you are checking several dosimeters, only remove one dosimeter at a time from its kit for each check. Keep all of the others in their kits so that they remain switched off.

3.2 Levelling of the base

	<p>Position the levelling base on a stable surface.</p>
	<p>Check the level</p>
	<p>Adjust the level along the first axis if necessary</p>
	<p>The bubble must be located between the 2 lines.</p>

	<p>Adjust the level along the other axis if necessary</p>
	<p>The levelling base is now level.</p>

3.3 Positioning of the device to be checked on the sensor frame

3.3.1 “Seat” sensor

Position the “seat” dosimeter in the area set aside for this purpose. Hold it in place using the mounting bar.



Figure 9: Positioning of the “seat” dosimeter on the sensor frame

3.3.2 “Floor” sensor

Position the “floor” dosimeter in the area set aside for this purpose. Hold it in place using the mounting bar.




Figure 10: Positioning of the “Floor” dosimeter on the sensor frame

	<p>There is a little room for manoeuvre within the space to be occupied by the “floor” sensor in order to take into account case machining tolerances.</p> <p>Use the white threaded clamp on the mounting bar to wedge the sensor into position.</p>
---	---

3.4 Running the check sequence

3.4.1 Connecting the sensor

Launch the WBCheck software and display the sensor selection screen.




Figure 11: Sensor selection screen

From the list, select the sensor that you wish to check.
Click “next”.

The software then connects to the selected sensor via Bluetooth.




Figure 12: Connecting the sensor

Following connection, the 6-position measurement sequence commences. The instructions are displayed under the heading of each window.

3.4.2 The 6 position measurements

Place the sensor frame in the X+ position and click “next”.




Figure 13: X+ position measurement

Return the sensor frame to the X- position and click “next”.




Figure 14: X- position measurement

Place the sensor frame in the Y+ position and click “next”.




Figure 15: Y+ position measurement

Return the sensor frame to the Y- position and click “next”.




Figure 16: Y- position measurement

Place the sensor frame in the Z+ position and click “next”.




Figure 17: Z+ position measurement

Return the sensor frame to the Z- position and click “next”.




Figure 18: Z- position measurement

3.5 Displaying the results

Following the measurement sequence along the 6 axis, the measurement results are displayed. They are expressed as a percentage error per axis. This percentage error must not exceed 4% (ISO8041 standard).




Figure 19: Results screen

You can then enter your name in the “Operator” field as well as a description of the check in the “Comment” field.




Figure 20: Validation of the check

You can then save the data relating to the check that you have just carried out by clicking on the  button. This is displayed in the “Previous test results” field.




Figure 21: Saving the calibration check data

By clicking on the  button, you can generate a report, print it and save it in various formats (Excel and pdf).

Section 4 - Updating of the WBCheck software

Each time the WBCheck software is launched and as long as your PC is connected to the internet, an available updates check is carried out.

If an update is available, a message is displayed prompting you to download it.

If for any reason you need to interrupt this update procedure, you can always download the new version of the software manually by accessing the link <http://www.vib-at-work.com/WBCheck/publish.htm>.



Please use Microsoft Internet Explorer to log on to the update website manually. The use of any other web browser may result in installation problems.

Section 5 - Support

If you encounter any problems with the installation or use of this product, support can be provided:

- Through your distributor (list on <http://www.vib-at-work.com> in the “distributors” section).
- By visiting the <http://www.vib-at-work.com> web site
- By sending an e-mail to support@micromega-dynamics.com

Manufactured by:



Micromega Dynamics SA

Parc Industriel de Noville-les-Bois

Rue du Trou du Sart, 10

B-5380 Fernelmont

Belgium

Tel. : +32(0)81 248 100

Fax: +32(0)81 248 101

Vib@Work is a registered trademark.